

Notice 300635603 served against Network Rail Infrastructure on 04/04/2007

Notice type	Improvement Notice		
Summary	Inadequate measures are in place at London Victoria station for identifying safe access routes across the roofs, in particular which roofs are fragile and which are not. Inadequate induction and permit to work arrangements for working at height.		
Recipient details	Network Rail Infrastructure Ltd 40 Melton Street London NW1 2EE		
Date Notice Served	04/04/2007		
Compliance date	06/07/2007	Revised compliance date	
Breaches involved in this notice	Health and Safety at Work Act 1974 Sections 2 (1) and 3 (1)		
Status of Notice	Open		

Location of offence

Address Victoria Station
London

ORR details

ORR Area Team Sussex and Wessex
ORR Directorate Railway Inspectorate